
DART AERO	SPACE LTD				Work Order:	41573		
7	193	11-5				50/5/2001	22	
Description:	OUTER	2 TUBF	TUBF *		Part Number:	PB6743001-2		
nspection Dwg: , Rev: ß\						Page 1 of 1		
OB 674	7/5/- 222							
110.	FIRST	ARTICLE IN	SPECTION	ON CHE	CKLIST	•		
	x	First Artic	First Article		otype			
Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments		
1.62	4- ,030	1.618	يد					
,663	4010	.062	Ør					
,005_								
		<u> </u>				1,4		
			 					
				<u> </u>		<u> </u>		
••								
	<u> </u>				-			
					·			
			, , , , , , , , , , , , , , , , , , , ,	· · · · · · · · · · · · · · · · · · ·			<u>.</u>	
·		·				<u>. </u>		
~··								
			-		<u> </u>	·	<u>-</u>	
		·						
		·						
		٠				<u>.</u>		
	1	é	·		·	•.		
		<u> </u>						
easured by:	烙	Audited by:		Pr	ototype Approv	al:		
Date:	8-9-8	Date:			Da	e:		
lev Date	Change				Revis	sed by Approv	red	
A Date	New issue	<u> </u>			KJ/JL	M		

XX	
1	
Ú,	



Dart Aerospace Ltd

		— - - -								
W/O:	.,		W	ORK ORDER CHAN	GES					
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval QC Inspector		
									·	
Part No: PAR #:		PAR #:	Fault Ca	tegory:	NCR: Yes No DQA: Date:					
		esolution:	Disposit	QA: N/C C	QA: N/C Closed:					
NCR:			WORK OR	DER NON-CONFORM	MANCE (NC	R)				
DATE	STEP	Description of NC Section A					cation	Approval	Approval	
			Initial Chief Eng	Action Description Chief Eng	n Sign Date		tion C	Chief Eng	QC Inspector	
					ļ					
									:	
								E	;	
				·						
	1	1							1	

NOTE: Date & initial all entries

Date:

Thursday, 21/08/2008 5:13:29 PM

User:

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: OUTER TUBE

Job Number: 41573

Part Number: PB6743001233

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QC21



FINAL INSPECTION/W/O RELEASE

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



Dart Aerospace Ltd

	•								
W/O:			WO	RK ORDER CHANG	ES				·
DATE	STEP		PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
,		, and the second			:	,			
						į			
								· · · · · · · · · · · · · · · · · · ·	
	,								
Part No: PAR #:		PAR #:	Fault Categ	ory:	_ NCR: Yes	No DQA		Date: _	
			Disposition:						
NCR:		٠.	WORK ORDE	R NON-CONFORM	ANCE (NCF	1)		, ,	
DATE	0.750	Description of NC			ion B	Verific	cation Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section		Chief Eng	QC Inspector
								į	
								;	
					:				

NOTE: Date & initial all entries

Each

Dart Aerospace Ltd. Thursday, 21/08/2008 5:13:29 PM Qate: User: Julie Lecocq **Process Sheet** : CU-DAR001 Dart Helicopters Services Customer **Drawing Name** : OUTER TUBE Job Number : 41573 **Estimate Number** : 13406 : PB6743001233 P.O. Number Part Number : B67-43001 P.20 : 21/08/2008 S.O. No. : This Issue **Drawing Number** Prsht Rev. : NC Project Number : N/A : // : SMALL/MED FAB : B1 First Issue Type **Drawing Revision** : 40043 **Previous Run** Material : 18/09/2008 **Due Date** Qty: 14 Um: Written By Checked & Approved By Comment : est rev A new issue 08.06.19 verified: EC **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** M6061T6S063 1.0 6061-T6 .063 Sheet Comment: Qty.: 0.0300 sf(s)/Unit Total: 0.4204 sf(s)6061-T6 .063 Sheet batch: 108379 WATER JET 2.0 FLOW WATER JET Comment: FLOW WATER JET 1-Cut as per Dwg B67-43001 Dwg Rev: 81 Prog Rev: 8 D08/08/11 @ lbm 2-Deburr if necessary 3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE 4.0 QC8 SECOND CHECK Comment: SECOND CHECK



PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location



